


El Don Sewer Replacement



Existing deteriorated and failing corrugated metal pipe (CMP) on El Don Drive.



Limits of sewer replacement (highlighted in yellow).